



# TOYOTA

## Warranty Policy Bulletin

I

No: POL92-01  
 Date: 11/01/91  
 Ref: \_\_\_\_\_

**SUBJECT: OXYGEN SENSOR REPLACEMENT ON 1988-1992 MODEL LIGHT DUTY TRUCKS**

In accordance with EPA standards Toyota covers the replacement of the oxygen sensor under warranty at the 80,000 miles maintenance service on specified 1988-1992 model light duty trucks.

The models covered by this program and claim preparation information are listed below.

<u>Model Year</u>	<u>Model</u>	<u>Model Code</u>	<u>Operation Code</u>	<u>Labor Hours</u>
1988 & 1989	Van	YR22W, YR26W, YR28V, YR29V, YR32W, YR36W, YR34V	001811	0.7
1991 & 1992	Previa	AC11R, AC12R, AC21S, AC22S	001811	0.7
1988	Truck	RN50A, RN55A, RN55R, RN55P, RN36S, RN56G, RN55T, RN63A, RN63S, RN64P, RN67P, RN67S, RN70A, RN70P, RN75T, RN75U, VN63C, VN63M, VN64N, VN67N, VN67M	001811	0.7
1989-1992	Truck	RN81A, RN81P, RN82P, RN82S, RN93P, RN93S, RN01P, RN01S, RN02P, RN13P, RN13S, VN82D, VN82N, VN82R, VN82T, VN93D, VN93G, VN94T, VN01D, VN01G, VN02D, VN13D, VN13G	001811	0.7
1988 & 1989	4Runner	RN62D, RN62S, RN63W, RN64W, VN62N, VN62M, VN66W	001811	0.7
1990-1992	4Runner	RN26S, RN27V, RN35S, RN36S, RN37J, RN37W, VN29V, VN35H, VN36H, VN39J, VN39W	001811	0.7
1988-1990	Land Cruiser	FJ62G, FJ62N	001811	0.7
1991 & 1992	Land Cruiser	FJ80W	001811	0.7

- Note: 1. Do not replace the sub-oxygen sensor in the tailpipe side on the Van and the Previa.  
 2. Replacement of both oxygen sensors is required on the Land Cruiser.

Should you have any questions, please contact the Warranty "800" Assistance Line at 1-800-421-3407 (49 states) or 1-800-421-3405 (California only).